



The Jonard Tools TK-184 Fiber Optic Connector Clean and Prep Kit offer cleaning and preparation products preparing fiber optic cable for splice-on connectors or any other fiber connector termination. The kit features the following:

- Fiber Stripper strips the 1.6-3 mm fiber jacket, 600-900 micron buffer coating, and 250 micron cable down to expose the 125 micron glass fiber
- Fiber Cleaver cleaves either 900 µm buffered or 250 µm coated fiber, the precision fiber cleaver provides a perfect cleave preparing fiber for fusion splicing
- Wet Wipes made with a nonabrasive residue-free 91% isopropyl alcohol solvent for cleaning the end-faces quickly and easily
- Visual Fault Locator identifies breakpoints, leaks, poor connections, and stress points in fiber optic cable
- Enclosed in our H-22 Rugged Carrying Case with Straps for safety and convenience
- Also includes our JIC-186 Kevlar Scissors and JIC-63020 for cutting kevlar and cables

**SPECIFICATIONS**

<b>DIMENSIONS</b>	10" x 5.5" x 5.0" (25.4 cm x 13.97 cm x 12.7 cm)
<b>UPC #</b>	810053352090

