



INSTRUCTIONS FOR MOUNTING JONARD TOOLS [CF-200](#) TO JONARD TOOLS [RDT-18K](#)



1. Select the 8-32 to 1/4-20 adapter that is provided with the [CF-200](#)
2. Screw the 8-32 end of the adapter into the hole on the top of the platform located on the [RDT-18K](#) Telescoping Pole



3. Screw the flexible gooseneck rod onto the 8-32 to 1/4-20 adapter
4. Screw the camera onto the end of the gooseneck as shown above