

MDS-100 MICRODUCT SHEATH SLITTING TOOL INSTRUCTION MANUAL

1



1. Start slitting at the end of your microduct.

2




2. Stop slitting when needed.

3



3. Do not lift up the MDS-100 while in microduct!
NOTE: Keep tool handle down to reduce stress on slitting guides.

4



4. Back out the MDS-100 to the end of the sheathe and remove it.

**MADE FOR LIFE
GUARANTEED FOR LIFE**